Does your system have breaks & leaks? It will. All water systems leak.









Wise Words:

"If I had only one hour to save the world, I would spend fifty-five minutes defining the problem, and only five minutes finding the solution."

~Albert Einstein

(There's no evidence he actually said this, but it's a solid concept.)





should we collect data?



To solve problems.



To answer questions.



will guide the 'what' and the 'how.'









Level of Service





Criticality





Life Cycle



Why



Funding

Asset Management

ASSETS

What assets do you manage, where are they, what condition are they in, what is their useful life, how much are they worth, and what is their energy use?

CRITICALITY

What is the overall business risk based on probability and consequence of asset failure? Is there redundancy to reduce risk?

FUNDING

Do you have funding sources to provide the capital you need for O&M, capital replacement and energy efficiency improvement?



SERVICE LEVEL

What level of service do you want to provide for your customers? How will you measure performance?

LIFE CYCLE

Is there a strategic plan for operating and maintaining system assets? Is a process, based on risk, in place to determine when to repair, rehabilitate or replace assets? Are you considering energy efficiency?



To improve decision making.



attributes do we collect?

attributes are relevant?





















was the Cause?

type of repair was done?





Tie breaks to location and specific pieces of pipe.

pictures Mai pictures pictures.
Image courtesy of the City of Virginia Beach

DEERE

Image courtesy of the City of Virginia Beach

Image courtesy of the City of Virginia Beach

Other useful Ward information can we get.







Financial What Social Environmental

Triple Bottom Line

can be verified?







Case Studies...





Level of Service



Improved Response Time



Goal set at 48 hrs: • 83% meet Goal (71% + 12%) • 17% miss Goal

17.00

CARL INCH

11- Peri

D'FIC

P SAID STOR

CAST (80%

1212942

E" CARLINGS

POAT NON

TO PHO DO PHO

141.00

C 254 317-18

enclust timple a lancada likible

T' CLET HILE

100

- 10.37 HILD

17.0A.07.145

-CACT (80)*

2"-IART PETRO

4" (04/3F) (P(0)

Stree.

£.



Water Loss Estimates





Put it all together:

(This is one of many orifice flow formulas)

$$Q = 449C_d A \sqrt{2gh}$$

Where:

- Q = flow (gmp)
- C_d= discharge coefficient
- A = orifice area (ft^2)
- $g = gravity (32.2 \text{ ft/s}^2)$
- h = head (ft)







Tracking Pipe Condition









->





Number of Breaks Year

Breaks vs Year





Criticality



PROBABILITY OF FAILURE

CONSEQUENCE OF FAILURE













Why



Funding


Effective use of budgeted funds.















Capital Improvement Planning

"We're going to replace our leaky system."

THE RYTEANT PRENER REPEATOR BUILTON CALATT BUILTING VALVE BUILTING VALVE AMPLIFIC LOCATION



type of repair was done?





The same attributes are relevant to many problems.



should I gather & store data?







1000

115AU

The Char





Address Or Location: ZEco Chumasol Date: January 18/2002 Time Reported: 8:00 And Water Main Size: 2" Type Of Water Main: Copper Service Depth: 6.0 Backfilled Used: Fill Dite Leak Caused By: Split: ____ Blow Out: ____ Hub Area: ___ Worned Out Bolts: ____ Service Saddle: ____ Galvanize Fittings: ____ Lead Joints: ____ Copper Fittings: ____ Old Repair Clamp: ____ Gaskets: ____ Other Related Problems Might Be: External Corrosion: ___ Pipe Deterioration: ___ Internal Pitting: ____ Surface Condition Street Surface: Paved Area: Unpaved Area: Vo Sidewalk Area: Driveway Area: Alleyway: Weather Conditions: Icy Roads: ___ Snowing: ___ Rained: ___ Windy: ___ Sunny: Yes Working At Night: ____ Office Information Reported By: Tina (Dispatcher)" Title: City Dispatcher. Previous Breaks In that Area: Yes Starting Time: 9:00 ME Ending Time: 10:30 AM Traffic Control Removed and Inventoried: Ves Area Of Town: East: West: South: North: Line Locate No. : 2002020627 Known Utilities: Gas: ___ Sewer: ___ Phone: 10 Water: ___ Electrical: ___ Cable TV. ___ Other: _____ perty Damage: None Crew Leader: Evnest Jun Unit 255 Stand-by Call: No Assigned by: P. Silve Leak Diagram Information ~ 2" METER Box

REPORT INFORMATION		TODAY'S DATE:	Feb 14, 2011 1:06 PM
REPORTED BY: METRO	NAMES:		PHONE #: 722-2002
ADDRESS: 210	2011 TIME REPORTED:	7:00 @ AM C PM	
TYPE OF CUSTOMER(S) AFFEC	TED: RESIDENTIA	A WEATH	IER: SUNNY
CONTACT NAME(S)			PHONE # :
ON-SITE INFORMATION	CONTACT PHO	ALE # I	
INVESTIGATED BY	INSUBANCE C		
C PRIVATE PLUMBING C DRIVATE S	EWER C EROZEN SERVICE C RELO	CATED METER BOX C INST	AULED BADIO BEAD METER
REPAIR INFORMATION			
CTADT DATE Eak 40 3044 CT	TART TIME: 7:00 (FAM C F	M ON CALL?: YES	FOLLOW UP?: NO
BU25WW	COMPLETION TIME 9.05	CAM @PM CALL	BACK7: NO
COMPLETION DATE: Feb 10, 2011	GOMPLE HOR TIME. 0.00		
COMPLETION DATE: Feb 10, 2017 COMPLETION DATE: Feb 10, 20 CREWMEN & UNIT(S) ON SITE:			
CREWMEN & UNIT(S) ON SITE:			
COMPLETION DATE: Feb 10, 20 COMPLETION DATE: Feb 10, 20 CREWMEN & UNIT(S) ON SITE: WE DIG UP 1ST TR COMMENTS: TO THE EAST 10 FT LINES EXPOSE TH INSTALLED (2) SAD	ENCH WATER STILL COMING OU T. OPEN 2ND TRENCH FOUND TH RE PIPE, (2) 1/4" HOLES ABOUT IDLES W. CORPS. THEN RE-ENE	IT FURTHER EAST SO W IE LEAK BETWEEN 2 GA 8° APART ON CAST IRO RIGIZED THE 4° LINE.	VE SPOT JUMPED MORE IS LINES & 2 SEWER N RIGHT NEXT TO HUB

Pictures? GPS? Other?

Use formats you can search and sort.

GIS Work order database Excel, etc.



can I gather data?



do I get GPS coordinates?





Your phone: turn on location services for the camera

Image details



0.0	Info		
Add a Title IMG_6476.JPG	inio		Ø
November 7, 2018	10:30:17	АМ	
Apple iPhone 6s		G	
iPhone 6s back c 3024 × 4032	amera 4.15 5.7 Mi	mm f/2.2 B	820
ISO 25 4.15mm	0 ev	f/2.2	1/761
Add a Description			
Add a Keyword			
+ Add Faces			
Albuquerque, New	Mexico, U	nited Sta	tes
Asto	eign iott iranhv		
	All and		
		C	opper Av
	11		
m The Marra			



4[1768].jpg

Photometric interpre	tation
Digital zoom	
EXIF version	0220
OF5	
Latitude	19; 29; 38.46110000000528
Longitude	154; 56; 41.30870000005217
Altitude	214.076
File	
Name	20180725_202714[1768].jpg
Item type	JPG File
Folder path	C:\Users\nallj\Pictures
Date created	9/24/2018 10:34 AM
Date modified	9/24/2018 10:34 AM
Size	3.58 MB
Attributes	A
Acres Barle States	

20180725_202714[1768].jpg Properties

General Security Details Previous Versions

Value

Auto

Property

Saturation Sharpness White balance

:::

Remove Properties and Personal Information

OK

Cancel

Apply



Image EXIF viewer app.

🖬 Verizon 🗟		2:39 PM	1:	26% 🗊		
<	IMC	G_6491.JPG	i -	Û	1SO 400	1
and the second		9	- AND	the second	\odot	3 P Bb
			heres		Evif \ lio	Linf
			a said			werlite
				0		
			No.	\mathbf{N}		
4032 x 3024	(4.9 MB)	Midtown - U	19 minute Iniversity,/	es ago Albu		
f/2.2	1/3	39 seconds	. 1	SO 25		
4 mm		X	iPho	one 6s		
Aperture (F-numbe	er)	f/2.2				
ISO Sensi	tivity	ISO 2	5			
Focal Len	gth	4 mm	6			
Focal Len 35 mm	gth in	29 mi	m			
Delete Photo	Remove Location	Remove EXIF	Edit EXIF	^		
All Photos	Albums	Favorites	Settings	(j) Heln		

📲 Verizon 🗢		2:27 PM	2	28%
<	IMG	_6492.JPG	i	Û
User Comm	ent			
Keywords				
Title				
Headline				
Caption				
GPS		35.08 -106.4	3389° 625167°	
GPS Direction	on	281.1 8 M	5756224	4518
Map Locatio	w we	XICO •	Open in M the	lap app Cente Univ
Delete Photo	Cemove ocation	Remove EXIF	Edit EXIF	^
All Photos	La bums	Favorites	Settings	(i) Help

📲 Verizon 🗢	2:31 PM	1	27% 🔳		
<	IMG_6494.JPC	3	Û	15O 400	÷
IMG_6494.J	PG R MRI Midtown	11 minute	es ago	ExifVie	wer
f/2.2	1/337 second	s l	SO 25		
4 mm	X	iPh	one 6s		
Aperture (F-number)	f/2.2				
ISO Sensitiv	rity ISO 2	25			
Focal Lengt	h 4 mm	n			
Focal Lengt 35 mm	h in 29 m	im			
			-		
Delete Photo	Remove Location Remove EXII	Edit EXIF	^		
All Photos Al	bums Favorites	Settings	(i) Help		

	Il Verizon		2:28 PM		28% 💷
	< Senairvur	IMC IDei	G_6493.JF	°G	Û
LITE	User Com	nment			
werLite	Keywords	5			
	Title				
	Headline				
	Caption				
	GPS		35.083370° -106.625197°		
	GPS Dire	ction	277.269958467928 M		
	Map Loca	tion		Open ir	мар арр
	Delete Photo	Remove Location	Remove EX	(IF Edit EXI	F
	All Photos	Albums	Favorites	Settings	(j) Help



Dropped Pin

....

near Central Campus, Albuquerque, NM, USA

Measure distance









Data format:

And							ده اینده اینده اینده اینده این
	1	J	ĸ	L	м	N	O format Haar 0
1		100	1005	Month	0.0240	5000	
2				January			for two instants
3				Jan			- Gradeet Inn
4				1			
5				01			
6				Jan			
7				1			
8				01			
9				January			
10							
11							
12							
13							

Data format:



Consistency matters. Apps can help you.

Use phone & tablet based collection apps.
fülcrum





How

How

fülcrum P	pe Bre	aks			00	eview App () UNM = ()
lields		Layout			Fields: 26	Settings
lanis						App Name
A Test	0	a) Work Order Number				Paralitaka
12 Nameric	θ	😥 Pge Amet D				Description
Ö Tes/Ne	0	F Pine Material				A ORIGINAL CONTRACTOR OF A DECIMAL
E Date	0					
Time (0	Fige Clameter			- 11	AppStatus ()
hoice		C Photos				Atter
Single Choice	0	(ii) Videas				The Shine Only Munders First S
Multiple Choice	0					23
Classification Field	0	(c) mm			- 11	Erubie Status Field O
wilge		🛛 🗄 Break Type	· · Label	Brud Tred		Natura Field Emailed)
Section .	0	1 Erech Cause	Description	A description of the type of tercoli.		Location Settings O
Repeatable	0	1 - Repair Tope		The second se	9	Location Settings (Enabled)
- Label	0		Default value	trusk fore		Card Contract
Media		I Longitudinal Crack Longth	Loca Harris	st Adox "Other"		Construction of the second sec
Signature	0	(g) Carrolian Hale Diameter (in)		Required held # Specify choices here Use a period related choice here		Save and Date - Save and Cardina
Photos	0	1 Circumference Grack Percentage	*			
Videos	0			Coule Cast		This app has existing data.
00 Audio	0	El comenciación de	Satt A-2	SartA-2		Tou can make changes to this form, but removing fields will cause relating data in these fields to
dvanced III Hole Size in Inches		10 Hole Size in Inches	Look at Junes Build Sear		become unavailable. If you need to make more than a few changes.	
Alfren	0	g 🚊 Candition of Pipe Near Break		Falge Rock implement		consider displicating the app before making your changes. See the information manual to least non- about how to use the app-designer
b Hyperlink	0	Data Reported		100		
Calculation	0	0.0.0				
Betale	0	C and approx		Linider?	2	
Becard Link	0	Trip Date Lask builded		E Read-only Reid?		
	-04	() Time Lask holisted		Li cersar la previsa vest:		
		(1) Date Repair Completed		Francisco Programme		
		() Time Repair Completed		Construction (Construction)		
				and the local division of the local division of the		

How

6:59 AM Tue Nov 13		· + 94% ■
Cancel	Pipe Breaks	Save
Work Order Number Test 1		
Pipe Asset ID M-842	Break Type	0
Pipe Material Cast Iron	Q. Search	• 0
Pipe Diameter	Circular Crack	•0
4	Corrosion 🗸	
Photos	Longitudinal Crack	•0
G	Leak at Joints	
	Bell Split	
	Fatigue	
Videos	Rock Impingement	0
	Other	
Audio		0
Ŷ	Clear Value	
Break Type Corrosion		0
Break Cause Pipe Failure		0
Repair Type Clamp		0
Corrosion Hole Diameter (in)		0
Condition of Dire New Break		
3 - Fair		v
	۲	















should we store attribute data?



Use formats you can analyze.





